

# Belzona Keeps the Cover on Annealing Oven

ID: 7566

Industry: *Steel & Metal Processing*

Customer Location: *Metallurgy Company, Slovakia*

Application: *ENC-Engines and Casings*


Application Date: *2011*

Substrate: *Iron*

Products: *Belzona® 1121 (Super XL-Metal)*

## Problem

*The cover had distorted and did not sit correctly on the base and caused a CO<sub>2</sub> leakage.*



## Photograph Descriptions

1. Annealing ovens
2. Surface preparation
3. Belzona® 1121 application
4. Cover replaced

## Application Situation

Large annealing oven at a metal manufacturing plant.

## Application Method

Application was carried out in accordance with Instructions for use.

## Belzona Facts

Using the Belzona solution allowed the original equipment to be used as a former, ensuring a perfect fit. Rebuilding in this way also meant the line was back up sooner than expected.

For more examples of Belzona Know - How In Action, please visit: <https://khia.belzona.com>

ISO 9001:2015  
Q 09335  
ISO 14001:2015  
EMS 509612

Belzona products are  
manufactured under an ISO  
9001 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve