

# Belzona Chocking Compound Stabilizes a Lathe

ID: 8393

Industry: *Steel & Metal Processing*  
Application: *GSS-Gaskets, Seals and Shims*  
Substrate: *Concrete, Steel*  
Products: *Belzona® 7111 (Industrial Grade)*

Customer Location: *Malacky, Slovakia*  
Application Date: *2020*

## Problem

*Lathe required a solution to withstand compressive load of machinery and reduce vibrations.*



## Photograph Descriptions

1. Installed lathe required a solid foundation
2. Temporary wood dam prepared
3. Pouring Belzona® 7111
4. Final application

## Application Situation

Installed lathe at a machine building manufacturer which required a solid foundation.

## Application Method

Application was carried out in accordance with Instructions for use.

## Belzona Facts

The Belzona solution secured the equipment for the long-term. Normally the machine would be bolted to the floor, which doesn't prevent corrosion or damage to the baseplate due to vibration.

For more examples of Belzona Know - How In Action, please visit: <https://khia.belzona.com>

ISO 9001:2015  
Q.09335  
ISO 14001:2015  
EMS 509612

Belzona products are  
manufactured under an ISO  
9001 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve